




# NUTS

## SQUARE AND HEX MACHINE SCREW NUTS



Nominal Size or Basic Thread Diameter		F			G		G1		H	
		Width Across Flats			Width Across Corners				Thickness	
					Square		Hex			
		Basic	Max.	Min.	Max.	Min.	Max.	Min.	Max.	Min.
2	0,086	3/16	0,188	0,180	0,265	0,247	0,217	0,205	0,066	0,057
3	0,099	3/16	0,188	0,180	0,265	0,247	0,217	0,205	0,066	0,057
4	0,112	1/4	0,250	0,241	0,354	0,331	0,289	0,275	0,098	0,087
5	0,125	5/16	0,312	0,302	0,442	0,415	0,361	0,344	0,114	0,102
6	0,138	5/16	0,312	0,302	0,442	0,415	0,361	0,344	0,114	0,102
8	0,164	11/32	0,344	0,332	0,486	0,456	0,397	0,378	0,130	0,117
10	0,190	3/8	0,375	0,362	0,530	0,497	0,433	0,413	0,130	0,117
12	0,216	7/16	0,438	0,423	0,619	0,581	0,505	0,482	0,161	0,148
1/4	0,250	7/16	0,438	0,423	0,619	0,581	0,505	0,482	0,193	0,178
5/16	0,313	9/16	0,562	0,545	0,795	0,748	0,650	0,621	0,225	0,208
3/8	0,375	5/8	0,625	0,607	0,884	0,833	0,722	0,692	0,257	0,239