




# NUTS

## "K" LOCK NUTS



Nominal Size or Basic Thread Diameter		F			G		H		I
		Width Across Flats			Width Across Corners		Thickness		Washer Diameter
					Hex				Ref.
		Basic	Max.	Min.	Max.	Min.	Max.	Min.	
4	0,112	1/4	0,250	0,241	0,289	0,275	0,098	0,087	0,281
6	0,138	5/16	0,312	0,302	0,361	0,344	0,114	0,102	0,344
8	0,164	11/32	0,344	0,332	0,397	0,378	0,130	0,117	0,375
10	0,190	3/8	0,375	0,362	0,433	0,413	0,130	0,117	0,406
1/4	0,250	7/16	0,438	0,423	0,505	0,482	0,193	0,178	0,500
5/16	0,313	1/2	0,500	0,489	0,577	0,557	0,273	0,258	0,578
3/8	0,375	9/16	0,562	0,551	0,650	0,628	0,385	0,365	0,656